



KELCH

Visualisierung CoVis




EN Brief instructions CoVis




1. Screen Display



Axis display







































2. Measuring Methods

| | |
|---|--|
|  | <p>1. Focussing: This relates to the edge focus, i.e. the highest point in X is determined. Move the tool edge into the camera's field of vision and position the edge behind the focus point. If necessary, adapt the focus window for focusing. Now turn the edge above the highest point until a red bar appears in the camera image. Subsequently turn back the edge until the bar turns green. Focus to X-min using CTRL+ Focus.</p> |
|  | <p>2. Total image: Move the tool edge into the camera's field of vision and activate the measuring type. Turn the tool (365°) to ensure the camera captures continuous images, placing them one above the other to display the contour left by the tool in the workpiece.</p> |
|  | <p>3. Projector mode: Use the fine setting to position the tool edge until the edge is precisely on the crosshairs.</p> |

3. Data Management Adapter/Holder





Position the setting mandrel or integrated calibration gauge in the camera image. Subsequently open the data management.

| | | | | | | | | | | | | | | | | | |
|---|---|---|----------------------------------|---|---|---|--------------------|--|------|---|------|---|------|---|------------|---|--------|
| <p>Total data management</p>  | <table border="0"> <tr> <td></td> <td>Adapter</td> <td></td> <td>New</td> </tr> <tr> <td></td> <td>Holder</td> <td></td> <td>Edit</td> </tr> <tr> <td></td> <td>Tool</td> <td></td> <td>Copy</td> </tr> <tr> <td></td> <td>Tool sheet</td> <td></td> <td>Delete</td> </tr> </table> |  | Adapter |  | New |  | Holder |  | Edit |  | Tool |  | Copy |  | Tool sheet |  | Delete |
|  | Adapter |  | New | | | | | | | | | | | | | | |
|  | Holder |  | Edit | | | | | | | | | | | | | | |
|  | Tool |  | Copy | | | | | | | | | | | | | | |
|  | Tool sheet |  | Delete | | | | | | | | | | | | | | |
| <p>Adapter data input mask</p>  | <p>Select adapter, enter adapter data and reference values, and select the calibration type. Then specify the zero point.</p> <table border="0"> <tr> <td></td> <td>Calibration type setting mandrel</td> </tr> <tr> <td></td> <td>Calibration type integrated calibration gauge</td> </tr> <tr> <td></td> <td>Specify zero point</td> </tr> </table> |  | Calibration type setting mandrel |  | Calibration type integrated calibration gauge |  | Specify zero point | | | | | | | | | | |
|  | Calibration type setting mandrel | | | | | | | | | | | | | | | | |
|  | Calibration type integrated calibration gauge | | | | | | | | | | | | | | | | |
|  | Specify zero point | | | | | | | | | | | | | | | | |
| <p>Holder input mask</p>  | <p>After defining an adapter, a holding fixture must be created for the adapter.</p> <p>Data Maintenance – Holding Fixture</p> <p>For example, it is possible to swap axes or alter the counting direction here.</p> <p>Furthermore, a correction value can also be entered, e.g. when using reduction sleeves which do not have a calibration edge. To achieve this, the engraved height is entered in the Offset field.</p> | | | | | | | | | | | | | | | | |








4. Data Management Tools/Tool Sheets

| | | |
|--|--------------|---|
| | | <p>New</p> <p>Edit</p> <p>Copy</p> <p>Delete</p> |
| | | <p>Absolute tolerance</p> <p>Tolerance difference</p> <p>Measure tool</p> <p>Save tool</p> |
| | | <p>New</p> <p>Edit</p> <p>Copy</p> <p>Delete</p> |
| | | <p>Accept tool from list</p> <p>Delete tool</p> <p>View tool sheet</p> <p>Save tool sheet</p> |

5. Search Beam Measurement




| | |
|--|---|
|  <p>Long press the button for selecting the search beam function. The beam search functions appear.</p> |  <p>Button for the search beam measurement diameter for a pre-determined length. Window opens for the set-point input.</p>  <p>Button for the search beam measurement length for a pre-determined diameter. Window opens for the set-point input.</p> |
|  | <p>After confirming the set-point input, the search beam is automatically placed on the edge. If necessary, move the edge into the camera image until the search beam is located directly on the edge.</p> |

6. Selecting the Measuring Functions




| | |
|---|---|
|  |  <p>Long press the button for selecting the measuring functions. The measuring functions appear.</p> |
|      | <p>Xmax/Zmax</p> <p>Theoretical intersection point</p> <p>Theoretical length</p> <p>Theoretical radius</p> <p>Theoretical apex</p> |

7. Separate Axis Measurement












Edge measurements during which the maximum X and Z value cannot be simultaneously captured in the measuring window (edges with a large radius >6 mm).

| | |
|--|---|
|  | <p>Approach the edge in the cross axis and then measure it. Press the  button on the axis display.</p> |
|  | <p>Approach the edge in the longitudinal axis and then measure it. Both axis values are now displayed.</p> |

8. Incremental (chain dimension zero point)

| | |
|---|---|
|  | <p> For example, when measuring a stepped tool from the tip to the step. Measure the tip, then press the button for setting the chain dimension zero point in the longitudinal axis.</p> |
|  | <p>Subsequently travel with the axes to the second measuring point and select the measurement task. The axis display now shows the incremental measuring value.</p> |

9. Additional Measurement Radius/Angle

| | |
|---|---|
| <p>Additional measurement selection</p>  |  <p>Press the plus button to attach another measurement.</p>  <p>Long press the additional measurement button. Further measurements are now displayed.</p> |
| <p>Radius</p>  |  <p>The camera captures the radius between two lines in the active window during this measuring task.</p> |
| <p>Circle sector</p>  |  <p>The camera captures the sector in the active window and calculates the best possible circle from all the visible points in the window.</p> |
| <p>Edge angle</p>  |  <p>The enclosed angle is captured.</p> |
| <p>General angle</p>  |  <p>Press the plus (+) button and then the button for the angle measurement, and, if necessary, adjust the measuring window.</p> |

10. Theoretical Apex

| | | |
|--|--|---|
| | | <p>Position the cutting lips in the camera image. Long press the button for selecting the measuring functions. Further measuring functions are now displayed.</p> |
| | | <p>Press the button for the theoretical apex and, if necessary, adjust the measuring window.</p> |

11. Theoretical Intersection Point

| | | |
|--|--|--|
| | | <p>Long press the button for selecting the measuring functions. Further measuring functions are now displayed.</p> |
| | | <p>Press the button for the theoretical intersection point and, if necessary, adjust the measuring window.</p> |

12. Edge Inspection


| | | |
|--|--|--------------------------------------|
| | | <p>Activate the edge inspection.</p> |
| | | <p>Zoom in and Zoom out.</p> |
| | | <p>Set the light sensitivity.</p> |

13. Data Back-Up

| | | |
|--|--|--|
| | | <p>Insert the USB stick. Long press the button for selecting the adapter zero point.</p> |
| | | <p>Subsequently select data back-up.</p> |
| | | <p>Save data.</p> |
| | | <p>Recover data.</p> |

14. Camera and Light Adjustment

Aligning the optical axis to the horizontal measuring plane



Holder for the camera

Holder for the transmitted light


This guarantees that the camera support is not tilted. Loosen the two screws at the camera support.

Then travel with the Z axis and the inserted mandrel down onto the plane surface of the spindle (see picture).

From the side, check the parallel gap between the plane surface and the mandrel.

Subsequently re-tighten the two screws.

Mounting the camera and light




Place the camera and the light into the holders and fix them into position. Check the correct alignment of the light with the aid of an aperture placed on the light (approx. 1 mm hole in the middle).

The light spot must be visible in the centre of the camera image. If necessary, you can readjust the light by slightly turning or tilting it.








Service mode display




Calc Pixel Size

This button opens the selection box for the angle and focus and light setting and for the pixel correction.


KELCH

| | |
|--|---|
| <p>Setting the light</p>  | <p>Calc Pixel Size</p> <p>Press the settings button.</p>  <p>Press the button for setting the light.</p> |
|  | <p>Unscrew the cover at the rear of the transmitted light and change the light at the potentiometer (see arrow) until the average is somewhere between 217 and 223.</p> |
| <p>Aligning the camera mandrel</p>  | <p>Use a dial gauge to align the camera mandrel until the calibrating edge is parallel to the cross axis. The alignment should be 2μ.</p> |
| <p>Setting the camera angle and focus</p>  | <p>Calc Pixel Size</p> <p>Long press the Calc Pixel Size button. The various setting tasks are now displayed.</p> <p>Sharpness And Angle</p> <p>Press the button for the focus and angle.</p> |



Position the camera mandrel as shown on the picture. Subsequently align the camera via the edge of the setting mandrel to ensure that the angle is as close to 0° as possible. Tolerance +/- 0.02°. At the same time, adjust the focus by moving the camera backwards and forwards. Ensure that the highest possible focus value is set.

Pixel correction




Calc Pixel Size

Press the Calc Pixel Size button, then travel to the lower right-hand window in the camera image with the setting mandrel.



>

Press the > button.



>

Now travel to the next window in the camera image and press the > button. Execute this process until you have travelled to all the positions.



A window appears with the calculated pixel correction values. Click on OK to confirm.